DMV Lane Technician Observation Report

DMV Technician: Kelly Dernell Position: Lor 2					
Station: New Castle Date: 9-30-13 Time:	: //	:15			
Vehicle Make: Chuy Model Nov	Year	19	77		
GVWR: Fuel Type: 649 Registration N	umber:	54	7077		
Auditor: (lour delu Covert Overt (circle one)					
	YES	NO	N/A		
1. Did technician check vehicle paper work and verify VIN number?	1				
2. Was Emissions testing required?	1				
a) Was Emissions testing performed using OBD?			1		
b) Was Emissions testing performed using Analyzer Probe?	V				
c) Was Emissions testing performed using Paddle(s)?			~		
d) Was Emissions testing performed using Clip?			V		
3. Was Catalytic Converter inspection required?	1				
a) Was Catalytic Converter inspection performed?	2				
4. Was Fuel Tank pressure testing required?					
a) Was Fuel Tank pressure testing performed?					
5. Was Fuel Cap pressure testing required?					
a) Was Fuel Cap pressure testing performed?					
6. Is this test a Re-check from a prior failure?		~			
a) Which re-check test is being performed? 1 2 3 (circle one)					
b) If this is re-check #3, was repair paperwork verified for waiver?					
New Castle and Kent Counties Only					
7. Was Two-Speed Idle testing required?		1			
a) Was Two-Speed Idle testing performed?					
Sussex County Only					
8. Was Curb Idle testing required?					
a) Was Curb Idle testing performed?					
Comment:					
CrB Take only- 1977					
Lane Supervisor Signature:					

Revised 04/12/2013

DMV Lane Technician Observation Report

DMV Technician: Holichy - James Position	on: Lor 2				
Station: New Ordtuc Date: 9-30-13 Time	Opotac Date: 9-30-13 Time: 10 40				
Vehicle Make: Prymon Model Appland	Year	1991	2		
GVWR: Fuel Type: Registration N	lumber:	XMY	27 150		
Auditor: Coverds he Covert Over	t (circle	one)	RII		
	YES	NO	N/A		
1. Did technician check vehicle paper work and verify VIN number?	1				
2. Was Emissions testing required?	V				
a) Was Emissions testing performed using OBD?					
b) Was Emissions testing performed using Analyzer Probe?	V				
c) Was Emissions testing performed using Paddle(s)?	V				
d) Was Emissions testing performed using Clip?					
3. Was Catalytic Converter inspection required?	2				
a) Was Catalytic Converter inspection performed?	1				
4. Was Fuel Tank pressure testing required?					
a) Was Fuel Tank pressure testing performed?					
5. Was Fuel Cap pressure testing required?			-		
a) Was Fuel Cap pressure testing performed?					
6. Is this test a Re-check from a prior failure?					
a) Which re-check test is being performed? 1 2 3 (circle one)					
b) If this is re-check #3, was repair paperwork verified for waiver?					
New Castle and Kent Counties Only					
7. Was Two-Speed Idle testing required?	L				
a) Was Two-Speed Idle testing performed?	1				
Sussex County Only					
8. Was Curb Idle testing required?					
a) Was Curb Idle testing performed?					
Comment: 18 3xA76 35L F G76095					
Lane Supervisor Signature:					

Revised 04/12/2013